

3 - Branch mispredict re-steer

2 - Exception/Fault re-steer

Multiplexer Priority: 1 - Debug/DFT IP

5 - '0 ' bubble branch re-steer 4 - '1' bubble branch re-steer

6 - Sequential IP (IP+1)

Figure 2

Prior Art

2207/10122 EL566655387US

N1/N2 - Inactive thread re-steer

3 - Branch mispredict re-steer4 - '1' bubble branch re-steer

2 - Exception/Fault re-steer

Multiplexer Priority: 1 - Debug/DFT IP 5 - '0 ' bubble branch re-steer 6 - Sequential IP (IP+1)

Figure 3

2207/10122 EL566655387US




Figure 4